




National Oil Spill Detection & Response Agency

Form A**OIL SPILL/LEAK NOTIFICATION REPORT***This report must be submitted within 24 hours of Spill Incidence*

1. GENERAL INFORMATION				
i. Company Name:		Mobil Producing Nigeria Unlimited		
II. Incident Details:		Date of Incident	Time of Incident (24h standard / daylight)	Time of Observation (24h standard / daylight)
iii. Spill reference No: 001/2020		19/06/2020	1119 hours	Date of Observation 19/06/2020 1119 hours
Survey By: Foot/Boat/ Helicopter / Overlook/			Sun / Clouds / fog / Rain / Snow / Windy	
Level of Impact: ☐ No Impact ☒ Slight Impact ☐ Heavy Impact				
Estimated quantity spilled: 0.000002 bbl of Diesel				
Probable Cause(s): During decanting of AGO at Mobil Annex Tank Farm seepage was observed on top of the soil covering the underground tank farm pipeline within minutes of decanting. Investigation ongoing to ascertain source of seepage. Precautionary measures taken since the spillage/leakage occurred to prevent hazards that may arise: Decanting was immediately discontinued and the area cordoned off. Consultant vendor invited to ascertain cause				
2. Site Details				
i. Site Name: Mobil Annex Lagos fuel tank farm				
ii. GPS FIELD POINTS Total Length:		Length Surveyed	Differential GPS Yes / No	
Spill Stat Point GPS: EASTINGS		NORTHINGS		
Spill End Point GPS: EASTINGS		NORTHINGS		
iii. Site area				
☐ Land Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline ☐ Near Shore				
☐ Offshore ☒ Others (specify): Soil (gravel / sand)				
iv. Containment Measures in Place				
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others				
v. Type of Contaminant				
☐ Crude oil ☐ Condensate ☐ Chemicals ☐ Refined Products ☒ Others: Diesel				
iv. Facility				
☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ SBM				
☐ Storage Tank Underground Pipeline ☐ Compressor Plant ☒ NONE :				
v. Properties at Risk				
☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water				
☐ Venerable Objects ☒ Others: Soil (gravel / sand)				
3. SURVEY TEAM NO				
Name		Organization		Phone Numbers
REPORTING OFFICER: Abiodun Lansebe				
DESIGNATION: Manager, Fuel Operations				
SIGNATURE:  DATE: June 20, 2020				
*RBA Report must be submitted within 24 Hours of the Spill Incidence.				