



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: FRONT

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) GAS LEAK

3. Incident Details

- i. Date of Incident: 09-11-2020 ii. Date first reported:
 iii. Date of first investigation: 13-11-2020
 iv. Date of follow-up investigation: 14-11-2020
 v. Time investigation started: 10:06am
 vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: CANAL II AKASO WEL 13H F/LINE @ CAPTAIN KIRI
 ii. Position of Spill/Leak: N 04° 31' 44.3" E 007° 01' 59.7"

iii. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock 15:30-6 O'clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) GAS LEAK

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) EXTERNAL CORROSION

v. Visible Sign of Third Party Interference

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) **MIA (GAS LEAK)**

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. i.
 ii. ii.
 iii. iii.
 iv. iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation. *Evotom to increase surveillance on the air facility.*

The JTI recommended sectional replacement of the floor lamp.

12. Time Investigation ended..... *10:59 hrs*