



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY

2. Type of Complaint/Incident:

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☒ Others (Specify) GAS LEAK

3. Incident Details

i. Date of Incident: 07 / 12 2020 ii. Date first reported: 07 / 12 / 2020

iii. Date of first investigation: 06 / 07 / 2021 iv. Spill Incident No: 2020/GLI/LAR/055/127

v. Date of follow-up investigation: / /

vi. Time investigation started: 1:30pm

vii. Estimated quantity spilled(bbls): NOT APPLICABLE viii. Quantity Recovered:

4. Site Details

i. Site/Location: 24" KWALE - AKRI PIPELINE @ ASEOMUKU

ii. State: DELTA iii. L.G.A: NDOUKWA - EAST

iv. Spill Co-Ordinates: N(m) 05° 39' 1.0"
E(m) 006° 33' 42.0"

v. Spill area

☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☒ Others (specify) SEASONAL SWAMP

iv. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) NOT APPLICABLE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☒ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☒ Others (specify) GAS LEAK

iii. Facility

☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)


iv. Cause of Spill

☐ Corrosion ☒ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☒ Others (specify) HUMAN ERROR

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (specify) NOT APPLICABLE



6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).... *NIL*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.... *NIL*

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others *NIL*

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten: 1. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 2. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 3. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 4. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten: 1. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 2. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 3. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 4. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten: 1. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 2. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 3. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 4. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten: 1. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 2. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 3. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>
<i>[Handwritten: 4. ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>	<i>[Handwritten: ...]</i>

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken N/A

11. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation NAOC SHOULD DO IMMEDIATE REPAIR
OF THE PIPE LINE

13. Time investigation ended 4:30pm

14. Name and Signature of _____