



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: TOTAL NIGERIA PLC

2. Type of Complaint/Incident:

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify).....

3. Incident Details

i. Date of Incident: 13th-12-2020 ii. Date first reported: 14th-12-2020

iii. Date of first investigation: 14th-12-2020

iv. Date of follow-up investigation: 16th-12-2020

v. Time investigation started: 11.50 Hours

vi. Estimated quantity spilled: 50 Metric tons

4. Site Details

i. Site/Location: Opp. Harbour Rd; Dockyard, Apapa

ii. Position of Spill/Leak: 6⁰⁰ o'clock

iii. Spill area

☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (specify)

iv. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O Clock ☐ 10 O Clock ☐ 2 O Clock ☐ 3 O Clock

☐ 4 O Clock ☐ 5 O Clock ☒ 6 O Clock

ii. Type of Oil contaminant

☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products (PMS)

☐ Others (specify)

iii. Facility

☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause Of Spill

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (specify)

Load of Sediment that resulted to Spill on the Pipeline.

☐Hacksaw Marks ☐Drilled Holes ☐Blasting ☐Theft ☐Acid

☐Others (specify).....

6. Impact of Incident

i Properties impacted by the incident

☐Farmland ☐Fish Pond ☐Vegetation ☐Fishing Net ☒Surface water

☐Venerable Objects ☐Others (specify)

ii. Nature of impact

☐Oil stained vegetation ☐Oil stained fishing nets ☐Dead floating fishes

☐Dead floating crabs ☐Withering of vegetation ☒Others.

iii. Delineation of impacted area

☒Within Company s facility/ROW ☐Outside Company s facility/ROW

7. Extent of Impact

a) Community (indicate name)

i.....

ii.....

iii.....

iv.....

b) Land (indicate area in m²)

i. 10-15 meter square.

ii.....

iii.....

iv.....

b) Creeks/Creek lets

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... None

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation Total Nig. REC. Should carry out
a Risk assessment of the area before carrying out
Seabeding and Detail work plan be forwarded to the Agency.

12. Time investigation ended. 1249 Hours

13. Name and Signature of Participants

❖ NOSDRA

1. Adamu A. P [Signature] SES.
2. A. O. JINDE [Signature] ESI
3. Olagunju Oladele [Signature] ESI

❖ DPR

- 1.
- 2.


❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY

1. TOTAL NIG. PLC - ERNEST UMUNNA 
2. TOTAL NIG. PLC - SAHIED GRADAMOSI 
- 3.

❖ COMMUNITY

- 1.
- 2.
- 3.

CC ECC — Enoch Olu Ibitoye 