

PHOTOGRAPHS TAKEN:



FIG A -B: Incident point on arrival (with notes dropped in plastic bottles by unknown persons)



FIG C: Impacted environment




FIG D: Content of note dropped on site by perpetrators



FIG E: Incident point on exposure



FIG F: Incident point after repairs