



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NACOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)
3. Incident Details
i. Date of Incident: 10 06 19 ii. Date first reported: 10 06 2019
iii. Date of first investigation: 12 06 19 iv. Spill Incident No: 2019/LAR/067
v. Date of follow-up investigation:
vi. Time investigation started: 14:58 HRS
vii. Estimated quantity spilled(bbls): 15 viii. Quantity Recovered: -NIL-
4. Site Details
i. Site/Location: 6" TUOMO-OGBOINBIRI DELIVERY LINE
ii. State: BAYELSA iii. L.G.A: EKEREMOR
iv. Spill Co-Ordinates: N(m) 04° 57' 51.1" 04° 57' 51.0"
E(m) 005° 55' 58.7" 005° 55' 58.7"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify)
- iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify)
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock COMPLETE RIP OFF
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☐ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)
iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify) ABOUT 1.3 METRES LENGTH OF
THE PIPELINE WAS HARVESTED (CUT OFF
AND CARRIED AWAY) BY UNKNOWN PERSONS



6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
☒ Fish Farm/ Pond
☒ Fishing Net
☒ Makeshift
☒ Permanent
☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. OGBOSUWARE
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>OGBOSUWARE</u>			

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

10. Samples taken.....

— NIL —

11. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

12. Remarks/Recommendation.....

A THREAT NOTE WAS LEFT ON SITE
BY PERSONS CLAIMING TO BE RESPONSIBLE FOR THE INCIDENT.

THIS THREAT SHOULD BE ADDRESSED BY NAOC

* AREA REQUIRES IMMEDIATE CLEANUP

13. Time investigation ended.....