



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: AITEO

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 07/09/2021 ii. Date first reported: 07/09/2021
iii. Date of first investigation: 17/09/2021
iv. Date of follow-up investigation:
v. Time investigation started: 12 noon
vi. Estimated quantity spilled: 204.15 BBL

4. Site Details

- i. Site/Location: ALONG NCTL ROW AT ELONA BLUE, R/S
ii. Position of Spill/Leak: 4.563611 N 6.8511889 E

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☒ Others (Specify) THEFT

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Cut Wire ☐ Cut Pipe ☐ Cut Cable
☐ Others (Specify) WELDED FLANGE & VALVE ON PIPELINE

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☐ Withering of vegetation
☒ Others (Specify) OIL ON WATER

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. ELOMA BILLE DEYEMA

ii. RIVERS STATE

iii. /

iv. /

(b) Land (Indicate area in m²)

i. 98,800 m²

ii. /

iii. /

iv. /

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by


☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation..... EFFECT IMMEDIATE REPAIRS OR AFFECT
PIPELINE AND IMPROVE SURVEILLANCE. ALSO ENSURE
CLEAN-UP AND RECOVERY OF ALL FREE PHASE OIL.

12. Time Investigation ended..... 4 : 00 PM

13. Name and Signature of Participants

❖ NOSDRA

1. OJUNGBE A. E  17/09/2021
2.