



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) NON-LEAK

3. Incident Details

- i. Date of Incident: 27/09/2021 ii. Date first reported: 27/09/2021
iii. Date of first investigation: 20/12/2021
iv. Date of follow-up investigation: N/A
v. Time investigation started: 13:50 HRS
vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: 14" OKORDIA - RUMUKEKE @ OSHIKA IN AHADA
ii. Position of Spill/Leak: N5.07138629 E6.5597089
iii. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify) N/A

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

6. Impact of Incident

i. Properties Impacted by the incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water

☒ Venerable Objects

☒ Others (Specify) N/A

ii. Nature of impact

☒ Oil stained vegetation

☒ Oil stained fishing nets

☒ Dead floating fishes

☒ Dead floating crabs

☒ Withering of vegetation

☒ Others (Specify) N/A

iii. Delineation of Impacted area

☒ Within Company's facility/ROW

☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

i.

i.

ii. OSHUKA

ii. N/A

iii. NO IMPACT

iii.

iv.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

9. Samples taken..... NIL

10. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

11. Remarks/Recommendation.....

Increase in surveillance in all facilities.

12. Time Investigation ended.....

15:30 HRS