

PICTURE SHOWING RUPTURED SECTION OF WELL 7 WELLHEAD AT OGBOINBIRI.



PICTURE SHOWING THE AFFECTED WELLHEAD AND ITS SURROUNDING BOOMED.

