



2020/SAR/059

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. **Company:** NAOC
2. **Type of Complaint/Incident:**
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. **Incident Details**
i. Date of Incident: 09/07/2020 ii. Date first reported: 09/07/2020
iii. Date of first investigation: 23/07/2020 iv. Spill Incident No.:
v. Date of follow-up investigation:
vi. Time investigation started: 10:08hrs.
vii. Estimated quantity spilled(bbls): 1 Bbl. viii. Quantity Recovered: NIL
4. **Site Details**
i. Site/Location:
ii. State: BAYELSA iii. L.G.A.: SOUTHERN IJAW
iv. Spill Co-Ordinates: N(m) 04° 49' 31.9"
E(m) 005° 58' 20.8"
v. **Spill area**
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
iv. **Structural Controls in Place**
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. **Circumstances Around Spill Point**
i. **Visual observation of Hole Position**
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. **Type of Oil contaminant**
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. **Facility**
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. **Cause of Spill**
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. **Visible Sign of Third Party Interference**
☒ Jacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☒ Fishing Net
 ☒ Makeshift
☒ Permanent
☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. OGIBON BIRU
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 11,981.14 m² (12 Ha)
= x (1.2 Ha.)
 ii.
 iii.
 iv.

b) Creeks/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... *NA*

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation.

NACE is requested to initiate immediate cleanup, and repair of the affected well head.

13. Time investigation ended.....

14. Name and Signature of Participants