



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NADP
2. Type of Complaint/Incident:
- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
- ☒ Others (Specify) Gas
3. Incident Details
- i. Date of Incident: 06/10/2020 ii. Date first reported: 06/10/2020
- iii. Date of first investigation: 06/10/2020 iv. Spill Incident No.: 2020/LAR/EL/047
- v. Date of follow-up investigation: N/A
- vi. Time investigation started: 12:00hrs
- vii. Estimated quantity spilled(bbls): NA viii. Quantity Recovered: NA
4. Site Details
- i. Site/Location: 6" Transoceanic N. of Anyanso
- ii. State: Bayelsa iii. L.G.A.: Ekeremor
- iv. Spill Co-Ordinates: N(m) 05 05 30.62
E(m) 006 54 44.10
- v. Spill area
- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
- ☐ Near shore ☐ Offshore ☐ Others (specify)
- iv. Structural Controls in Place
- ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify) N.A
5. Circumstances Around Spill Point
- i. Visual observation of Hole Position
- ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
- ☐ 4 O' Clock ☐ 5 O' Clock ☒ 6 O' Clock 9 o'clock
- ii. Type of Oil contaminant
- ☐ Crude Oil ☒ Condensate ☐ Chemicals ☐ Refined Products
- ☐ Others (specify)
- iii. Facility
- ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
- ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
- iv. Cause of Spill
- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
- ☐ Operational Error ☐ Others (specify)
- v. Visible Sign of Third Party Interference
- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
- ☐ Others (specify)

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☒ Others (specify)..... **NO VISIBLE IMPACT**

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☒ Others..... **Nil**

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others..... **NA**

8. Extent of Impact

a) Community (indicate name)

- i. **Anyang**
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal ☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation.....

NAC should be requested to strengthen the surveillance on their facility.

13. Time investigation ended.....

14. Name and Signature of Participants

❖ NOSDRA