



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NAOC LTD.
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 8 / 11 / 2020 ii. Date first reported: 8 / 11 / 2020
iii. Date of first investigation:..... iv. Spill Incident No:.....
v. Date of follow-up investigation:.....
vi. Time investigation started:.....
vii. Estimated quantity spilled(bbls): 298 Bbls viii. Quantity Recovered: 295 Bbls
4. Site Details
i. Site/Location: DEHYDRATION UNIT, BRASS THERMATE
ii. State: BAYELSA iii. L.G.A.: BRASS
iv. Spill Co-Ordinates: N(m). 04° 17' 55.80"
E(m). 006° 14' 52.23"
v. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
- iv. Structural Controls in Place
☐ Boom ☐ Trenches ☒ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock OVERFLOW OF DEHYDRATION UNIT.
- ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify).....
- iii. Facility
☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☒ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
- iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☒ Operational Error ☐ Others (specify).....
- v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☒ Others (specify) DELAY STARTING SWITCHING ON OIL TRANSFER PUMP DURING MANUAL OPERATION.

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☒ Others (specify)... NA

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☒ Others... NA

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☒ Others

8. Extent of Impact

a) Community (indicate name)

- i. NAOZ TERMINAL
 ii. (BRASS TERMINAL)
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

10. Samples taken..... NA

11. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation..... CLEAN up of oil impacted
AREAS REQUIRED.

13. Time investigation ended.....

14. Name and Signature of Participants