

3080460



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: S P D C

2. Type of Complaint/Incident:

☐ Oil Pollution

☐ Fire/Explosion

☐ Drilling Mud/Chemical Pollution

☐ Others (Specify) NON LEAK

3. Incident Details

i. Date of Incident: 14/01/2022

ii. Date first reported: 15/01/2022

iii. Date of first investigation: 24/01/2022

iv. Date of follow-up investigation: _____

v. Time investigation started: 1153 HRS

vi. Estimated quantity spilled: NON LEAK INCIDENT

4. Site Details

i. Site/Location: 20" Rumu Ekpe - Nkpoku P/L @ OGIBODO ISIKOKPO

ii. Position of Spill/Leak: N 4° 57' 10.2", E 6° 51' 36.1"

iii. Spill area

☐ Land

☐ Swamp

☐ Freshwater

☐ Mangrove

☐ Coastline

☐ Near shore

☐ Offshore

☐ Others (Specify) N/A

iv. Structural Controls in Place

☐ Boom

☐ Trenches

☐ Bund Wall

☐ Sorbents

☐ Others (Specify) _____

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O'Clock

☐ 10 O'Clock

☐ 2 O'Clock

☐ 3 O'Clock

☐ 4 O'Clock

☐ 5 O'Clock

☐ 6 O'Clock

ii. Type of Oil Contaminant

☐ Crude Oil

☐ Condensate

☐ Chemicals

☐ Refined Products

☐ Others (Specify) NON LEAK

iii. Facility

☒ Pipeline

☐ Flow Line

☐ Wellhead

☐ Manifold

☐ Flow Station

☐ Rig

☐ Storage Tank

☐ Compressor Plant

☐ Others (Specify) _____

iv. Cause of Spill

☐ Corrosion

☐ Equipment Failure

☒ Third Party Interference

☐ Accident

☐ Operational Error

☐ Others (Specify) _____

v. Visible Sign of Third Party Interference

☐ Hack saw Marks

☐ Drilled Holes

☐ Blasting

☒ Theft

☐ Acid

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) N/A

ii. Nature of Impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) N/A

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i. _____
 ii. N/A
 iii. _____
 iv. _____

(b) Land (Indicate area in m²)

- i. _____
 ii. N/A
 iii. _____
 iv. _____

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

SPDC SHOULD INTENSIFY
SURVEILLANCE ON THEIR FACILITIES AND REPAIR
INCIDENT POINT IMMEDIATELY

12. Time investigation ended. 1759 HRS