

3082461

# NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: S.P.D.C

2. Type of Complaint/Incident:

☐ Oil Pollution

☐ Fire/Explosion

☐ Drilling Mud/Chemical Pollution

☐ Others (Specify) NON LEAK

3. Incident Details

i. Date of Incident: 26/01/2022

ii. Date first reported: 26/10/2022

iii. Date of first investigation: 27/01/2022

iv. Date of follow-up investigation:

v. Time investigation started: 11:35 HRS

vi. Estimated quantity spilled: NON LEAK INCIDENT

4. Site Details

i. Site/Location: 20" RUMUETKE-NKPOKU P/L @ OUBODO KSIKPO

ii. Position of Spill/Leak: N 4° 57' 10.1", E 6° 51' 39.0"

iii. Spill area

☒ Land

☐ Swamp

☐ Freshwater

☐ Mangrove

☐ Coastline

☐ Near shore

☐ Offshore

☐ Others (Specify) .....

iv. Structural Controls in Place

☐ Boom

☐ Trenches

☐ Bund Wall

☐ Sorbents

☐ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O'Clock

☐ 10 O'Clock

☐ 2 O'Clock

☐ 3 O'Clock

☐ 4 O'Clock

☐ 5 O'Clock

☐ 6 O'Clock

ii. Type of Oil Contaminant

☐ Crude Oil

☐ Condensate

☐ Chemicals

☐ Refined Products

☐ Others (Specify) NON LEAK

iii. Facility

☒ Pipeline

☐ Flow Line

☐ Wellhead

☐ Manifold

☐ Flow Station

☐ Rig

☐ Storage Tank

☐ Compressor Plant

☐ Others (Specify) .....

iv. Cause of Spill

☐ Corrosion

☐ Equipment Failure

☒ Third Party Interference

☐ Accident

☐ Operational Error

☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks

☐ Drilled Holes

☐ Blasting

☒ Theft

☐ Acid

☐ Others (Specify) .....

- i. Properties Impacted by the spill
- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
- ☐ Venerable Objects ☐ Others (Specify) N/A
- ii. Nature of impact
- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
- ☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) N/A
- iii. Delineation of Impacted area
- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

### 7. Extent of Impact

(a) Community (Indicate name)

i. N/A

ii. N/A

iii. N/A

iv. N/A

(b) Land (Indicate area in m<sup>2</sup>)

i. N/A

ii. N/A

iii. N/A

iv. N/A

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A .....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. SPDC SHOULD INTENSIFY  
SURVEILLANCE ON THEIR FAULTIES AND REPAIR  
INCIDENT POINT IMMEDIATELY

12. Time Investigation ended... 18:14 HRS .....