



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify) WATER

3. Incident Details

- i. Date of Incident: 29-06-2022 ii. Date first reported: 30-06-2022
iii. Date of first investigation: 02-07-2022
iv. Date of follow-up investigation: 04/07/2022 and 16-18/07/2022
v. Time investigation started:
vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: 28" BOMU-BUNNY TNP @ ALGBA + OKWAN ASARAMA (FREETOWN)
ii. Position of Spill/Leak: N 4.527564 E. 7.241838

iii. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock ☒ 11 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify) WATER

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hack saw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others (Specify)

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW
 ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. OURA-DIWAN ASARANA

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i.

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken..... NIL

10. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation..... UPPER REPAIRS AND PENDING WITH RESULT
CARRY OUT PERMANENT REPLACEMENT OF CORRODED PIPELINE

12. Time Investigation ended.....

13. Name and Signature of Participants

❖ NOSDRA

1. DRUNGIDE A - E ~~meat~~ 18/07/2012
2.
3.