

508057



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SPDC
2. Type of Complaint/Incident:
 - ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify) NOW-LEAK (ILLEGAL CONNECTION)
3. Incident Details
 - i. Date of Incident: 10-07-22 ii. Date first reported: 10-07-2022
 - iii. Date of first investigation: 20-07-2022
 - iv. Date of follow-up investigation: —
 - v. Time investigation started: 12:30 Hrs
 - vi. Estimated quantity spilled: N/A
4. Site Details
 - i. Site/Location: 36" Runnup type - NIKOKU pipeline at Runnup.
 - ii. Position of Spill/Leak: N 4.95485963, E 6.788447
 - iii. Spill area
 - ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify) AT
 - iv. Structural Controls in Place
 - ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) N/A
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify) N/A
 - iii. Facility
 - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify) —
 - iv. Cause Of Spill
 - ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify) —
 - v. Visible Sign of Third Party Interference
 - ☐ Jacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
 - ☐ Others (specify) —

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) N/A

ii. Nature of Impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) N/A

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii. N/A
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii. N/A
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		<u>N/A</u>	

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		<u>N/A</u>	

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		<u>N/A</u>	

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		<u>N/A</u>	

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation *JIN completed, Repairs should be effected on the hull by SPDC, more surveillance on the facility.*

12. Time Investigation ended.....