



PICTURE A: SHOWING BLASTED PORTION OF THE RISER AT 12 O' CLOCK POSITION.
PICTURE B: SHOWING REPAIRED SECTION OF THE RISER.



PICTURE C: SHOWING CRUDE OIL FROM THE BLASTED RISER ENTERING THE OPEN RIVER.
PICTURE D: SHOWING A WHITE FLAG ON WHICH THE PERSON/GROUP THAT BLASTED THE RISER WROTE THE REASON BEHIND THEIR ACTIONS.