



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC) LTD
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 11 / 08 / 22 ii. Date first reported: 11 / 08 / 22
iii. Date of first investigation: 11 / 08 / 22 iv. Spill Incident No.: 2022/SAR/078
v. Date of follow-up investigation: 11 / 08 / 22
vi. Time investigation started: 1345hrs
vii. Estimated quantity spilled(bbls): 20 viii. Quantity Recovered: 3
4. Site Details
i. Site/Location: 14" OGBONBIRI/TEBIDABA P/L @ IKENBIRI
ii. State: BAYELSA iii. L.G.A.: SOUTHERN IJAW
iv. Spill Co-Ordinates: N(m) 04° 43' 26.1"
E(m) 005° 58' 20.0"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....

6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☒ Others (specify) NOT APPLICABLE

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others NOT APPLICABLE

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
☒ Fish Farm/ Pond
☒ Fishing Net
☒ Makeshift
☒ Permanent
☒ Others NOT APPLICABLE

8. Extent of Impact

a) Community (indicate name)

- i. _____
 ii. _____
 iii. _____
 iv. _____

b) Land (indicate area in m²)

- i. _____
 ii. _____
 iii. _____
 iv. _____

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... NOT APPLICABLE.....

11. Investigation carried out by
☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation 3" VALVE AND PIPE CONNECTION
WAS OBSERVED ON FACILITY AT 12 O'CLOCK
POSITION FOR OIL THEFT ACTIVITY.....

13. Time investigation ended.....