

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

1. Company: NIGERIAN AERIAL OIL COMPANY (NAOC) LTD
2. Type of Complaint/Incident:  
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify).....
3. Incident Details  
i. Date of Incident: 15/06/22 ii. Date first reported: 15/06/22  
iii. Date of first investigation: 16/06/22 iv. Spill Incident No: 2022/SAR/052  
v. Date of follow-up investigation: 16/06/22  
vi. Time investigation started: 1600HRS  
vii. Estimated quantity spilled(bbls): 20 viii. Quantity Recovered: 3
4. Site Details  
i. Site/Location: 14" OGBUNBARI/TEBIDIBA P/L @ OKPOTUWARI  
ii. State: BAJEL SA iii. L.G.A: SOUTHERN IJAW  
iv. Spill Co-Ordinates: N(m) 04° 45' 35.5"  
E(m) 005° 58' 39.3"  
v. Spill area  
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline  
☒ Near shore ☒ Offshore ☒ Others (specify).....
- iv. Structural Controls in Place  
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock  
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock  
ii. Type of Oil contaminant  
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products  
☒ Others (specify).....  
iii. Facility  
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig  
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....  
iv. Cause of Spill  
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident  
☒ Operational Error ☒ Others (specify).....  
v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid  
☒ Others (specify).....



## 6. Impact of Incident

### i Properties impacted by the incident

- ☒ Farmland 
 ☒ Fish Pond 
 ☒ Vegetation 
 ☐ Fishing Net 
 ☐ Surface water 
 ☒ Venerable Objects 
 ☒ Others (specify) N/A

### ii. Nature of impact

- ☒ Oil stained vegetation 
 ☒ Oil stained fishing nets 
 ☒ Dead floating fishes 
 ☒ Dead floating crabs 
 ☒ Withering of vegetation 
 ☒ Others N/A

### iii. Delineation of impacted area

- ☒ Within Company's facility/ROW 
 ☒ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops 
 ☒ Fish Farm/ Pond 
 ☒ Fishing Net 
 ☒ Makeshift 
 ☒ Permanent 
 ☒ Others NOT APPLICABLE

## 8. Extent of Impact

### a) Community (indicate name)

- i. /  
 ii. /  
 iii. /  
 iv. /

### b) Land (indicate area in m<sup>2</sup>)

- i. /  
 ii. /  
 iii. /  
 iv. /

### b) Creeks/Creek lets

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

10. Samples taken..... NOT APPLICABLE .....

11. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

12. Remarks/Recommendation. A 3" NIPPLE WAS SEEN  
INSTALLED ON FACILITY @ 12 O'CLOCK  
POSITION FOR OIL THEFT ACTIVITIES .....

13. Time investigation ended.....