

PHOTOGRAPHS TAKEN DURING JIV AT 18"TEBIDABA/BRASS PIPELINE AT ELEPA
SOUTHERN IJAW LOCAL GOVERNMENT AREA, BAYELSA STATE.



FIG. 1 SHOWING SPILL POINT (BEFORE REPAIR)



FIG.2 SHOWING SPILL POINT (AFTER REPAIR)



Figure 3 REPAIRED