



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: Nigerian Agip Oil Company (NAOC)

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 21/09/2022 ii. Date first reported: 21/09/2022
iii. Date of first investigation: 21/09/2022
iv. Date of follow-up investigation:
v. Time investigation started: 1600 Hrs
vi. Estimated quantity spilled: 266L

4. Site Details

- i. Site/Location: 18" Ebocha-Ogoda Pipeline Ubeta Community
ii. Position of Spill/Leak: N 05° 10' 10.4" E 06° 35' 25.3"

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) Natural Containment

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock ☒ 11-2 O'clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. Ubeta Community

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. 284.04 m²

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation.....

.....

.....

12. Time Investigation ended..... *1715 HRS*