

APPENDIX I

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT (JIV)




Fig A. SPILL POINT BEFORE EXCAVATION



Fig B. SPILL POINT AFTER REPAIR