



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SHELL PETROLEUM DEVELOPMENT COMPANY
2. Type of Complaint/Incident:
☐ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)
3. Incident Details
i. Date of Incident: 25. 07.2021 ii. Date first reported: 25. 07.2021
iii. Date of first investigation: 05.10.2022 Spill Incident No.: 2841950
v. Date of follow-up investigation: N/A
vi. Time investigation started: 1520 HRS
vii. Estimated quantity spilled(bbls): N/A viii. Quantity Recovered: N/A
4. Site Details
i. Site/Location: 20' OPUKUSHI/BRASS CREEK P/L AT TAMOGIBENE
ii. State: BORNO iii. L.G.A: EKEREMOR
iv. Spill Co-Ordinates: N(m): 4.9352510
E(m): 5.7112487
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify)
- iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify)
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)
- iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)
- iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify)
- v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify)



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
 ☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
 ☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☒ Fishing Net
 ☒ Makeshift
 ☒ Permanent
 ☒ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A			

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A			

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A			

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A			

☒ Still photographs

☒ Video coverage

☒ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

12. Remarks/Recommendation SHELL PETROLEUM DEVELOPMENT
COMPANY INTENSIFY THEIR SURVEILLANCE
CASES TO MAINTAIN A GREENER ENVIRONMENT

13. Time investigation ended.....