



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution
 ☐ Fire/Explosion
 ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 23/09/2022
 ii. Date first reported: 23/09/2022
 iii. Date of first investigation: 23/09/2022
 iv. Date of follow-up investigation:
 v. Time investigation started: 14:00 HRS
 vi. Estimated quantity spilled:

4. Site Details

- i. Site/Location: 24" OGODA - BRASS PL AT OSHIKA AHEAD WESI LG
 ii. Position of Spill/Leak: 12 - 2 O'Clock

iii. Spill area

- ☒ Land
 ☐ Swamp
 ☐ Freshwater
 ☐ Mangrove
 ☐ Coastline
☐ Near shore
 ☐ Offshore
 ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom
 ☒ Trenches
 ☒ Bund Wall
 ☐ Sorbents
 ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock
 ☐ 10 O'Clock
 ☒ 2 O'Clock
 ☐ 3 O'Clock
☐ 4 O'Clock
 ☐ 5 O'Clock
 ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil
 ☐ Condensate
 ☐ Chemicals
 ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline
 ☐ Flow Line
 ☐ Wellhead
 ☐ Manifold
 ☐ Flow Station
 ☐ Rig
☐ Storage Tank
 ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion
 ☐ Equipment Failure
 ☒ Third Party Interference
 ☐ Accident
☐ Operational Error
 ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks
 ☐ Drilled Holes
 ☐ Blasting
 ☐ Theft
 ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. Ostika Community

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. 1169.45 m²

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken... *N/A*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

*NACC SHOULD COMMENCE CLEAR-UP
AND RECOVERY, WITHIN TWO WEEKS FROM THE
JIV DATE.*

12. Time Investigation ended... *17:00 HRS*