



PNC. No. 725 785

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: Shell Petroleum Dev. Company

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) Theft point / Illegal Installation

3. Incident Details

- i. Date of Incident: 6/11/2022 ii. Date first reported:
iii. Date of first investigation: Nov. 17, 2022
iv. Date of follow-up investigation:
v. Time investigation started: 12:43 PM
vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: 28" TNP at Norkpo
ii. Position of Spill/Leak: N04° 44' 28.5" E 007° 11' 37.9"
iii. Spill area / No Spill

- ☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) Not Applicable

5. Circumstances Around Spill Point

i. Visual observation of Hole Position / Theft Point

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock 9 O'clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) No Contaminant Spilled

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill / No Leak

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify) 2" ball valve installed on 28" pipeline

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) ... None

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) ... not Applicable

iii. Delineation of Impacted area /No Impact

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken *Not Applicable*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. *① Repairs of the affected facility should be carried out. ② Facility should be strengthened along the Right of Way.*

12. Time Investigation ended.....

13. Name and Signature of Participants

❖ NOSDRA
1. *Ukpenevi Solomon* *[Signature]* 17/11/2022

2.
3.

❖ DPR
1.
2.
3.

❖ STATE MINISTRY OF ENVIRONMENT
1. *OLGBABA, D. TONYE* *[Signature]* 17/11/2022
2.
3.

❖ LOCAL GOVERNMENT COUNCIL
1.
2.
3.

❖ COMPANY
1. *SHEDY, TIJANI (SPDC)* *[Signature]* 17/11/2022
2. *CAMEN PETER (SPDC)* *[Signature]* 17/11/2022
3.

❖ COMMUNITY 'NORRPOR
1. *BARILERA ABIE S.* *[Signature]* 17/11/2022
2. *NPIERNE ERNEST NERKA* *[Signature]* 17/11/2022.
3.