

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... None

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. NAOC should be mandated to clean-up
the area with the supervision of the Agency. The Company
should also be advised to intensify Pipeline Surveillance in their
facilities

12. Time Investigation ended..... 3:05 pm

13. Name and Signature of Participants