



Inc No: 825253

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☐ Others (Specify) Non-Leak

3. Incident Details

- i. Date of Incident: 11/01/23 ii. Date first reported: 5/01/23
iii. Date of first investigation: 16/01/23
iv. Date of follow-up investigation: _____
v. Time investigation started: 15:46 Hrs
vi. Estimated quantity spilled: Non-Leak

4. Site Details

- i. Site Location: 20" Kolocreek - Rumueke TL @ Rumueke, Enugu LGA
ii. Position of Spill/Leak: N497108 E6642346

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify) Non-Leak

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☐ Others (Specify) _____

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) Non-Leak

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify) _____

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) _____

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify) About 30cm Casted Cement at 12 O'clock

6. Impact of Incident

i. Properties Impacted by the incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☐ Surface water
☒ Venerable Objects ☐ Others (Specify) ADO-12215

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

i. Remedial i.
 ii. ii.
 iii. iii.
 iv. iv.

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

1. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

2. Samples taken N/A

3. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

4. Remarks/Recommendation

SPDC should improve on its surveillance
to curb imminent third party intelligence by engaging
the services of the local security outfit

5. Time investigation ended

6. Name of Investigator