



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NACC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 13-2-2023 ii. Date first reported: 13-2-2023
iii. Date of first investigation: 13-2-2023
iv. Date of follow-up investigation: N/A
v. Time investigation started: 13/2/23
vi. Estimated quantity spilled: 1.25 barrels

4. Site Details

- i. Site/Location: 13" Etoch9 - Ogoni P/L AT DWIKE ANWELGA
ii. Position of Spill/Leak: N05° 12' 03.7", E008° 55' 25.0"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

11-12° clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Floating Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) _____

ii. Nature of Impact

- ☒ Oil stained vegetation ☐ Oil stained floating nets ☐ Dead floating fishes
 Dead floating crabs Withering of vegetation Others (Specify) _____

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. SKUBU

ii. _____

iii. _____

iv. _____

(b) Land (Indicate area in m²)

i. 191.73 m²

ii. _____

iii. _____

iv. _____

(c) Creek/Creeklets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK
	N	A	

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK
	N	A	

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK
	N	A	

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK
	N	A	

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation ① NAOC should improve on their surveillance in order to abate re-occurrence
② NAOC should commence clean-up with immediate effect

12. Time Investigation ended..... 1415 hrs

13. Name and Signature of Participants

❖ NOSDRA

1. ONWUEGBUIE NNAMDI 13-2-2023
2.
3.

❖ NUPRC/NMDPRA

1.
2.
3.

❖ STATE MINISTRY OF ENVIRONMENT

1. EBIANGA DAPPA 13-02-2023
2.
3.

❖ LOCAL GOVERNMENT COUNCIL

1.
2.
3.

❖ COMPANY

1. THEJIRIKA DAULINUS-C 13/02/23
2.
3.

❖ COMMUNITY

1. Allen D. 13/02/2023
2.
3.