

2023/LAR/038



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: 2023/LAR/ NAD C
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 23/01/23 ii. Date first reported: 23/01/2023
 - iii. Date of first investigation: 23/01/2023
 - iv. Date of follow-up investigation:.....
 - v. Time investigation started: 1441 hrs
 - vi. Estimated quantity spilled: 2-3 bbls
4. Site Details
 - i. Site/Location: 18th EBOCHA - OGODA P/L @ DWURE ANWELGA
 - ii. Position of Spill/Leak: N05° 12' 12.8 E006° 35' 26.2"
 - iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
 - iv. Structural Controls in Place
☐ Boom ☒ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☐ 12 O' Clock ☒ ^{10-11 O' Clock} 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
 - iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. OWUBE
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 52.07
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N</u>	<u>1A</u>	

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N</u>	<u>1A</u>	

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N</u>	<u>1A</u>	

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N</u>	<u>1A</u>	

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation... ① NADC SHOULD IMPROVE DN SURVEILLANCE

② NADC SHOULD REPAIR AFFECTED FACILITY.....

③ NADC SHOULD EMBARK ON RECOVERY OF FREE PHASE OIL

12. Time investigation ended..... 15:50 PM

13. Name and Signature of Participants

❖ NOSDRA

1. ONWUEGBUZIE, NWANDI FRANK [Signature] 23/01/2023

2.

3.

❖ DPR

1. /

2. /

3. /

❖ STATE MINISTRY OF ENVIRONMENT

1. EBIANGA DAPPA [Signature] 23/01/2023

2.

3.

❖ LOCAL GOVERNMENT COUNCIL

1.

2.

3.

❖ COMPANY

1. AKPERU GO E FESTUS [Signature] 23/01/2023

2. AKPE CHRISTIAN [Signature] 23/01/2023

3.

❖ COMMUNITY

1. OKPARA KELVIN [Signature] 23/1/2023

2.

3.