



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☐ Others (Specify) NON-LEAK ILLEGAL CONNECTION

3. Incident Details

- i. Date of Incident: 17/2/2023 ii. Date first reported: 17/2/2023
 iii. Date of first investigation: 20/2/2023
 iv. Date of follow-up investigation:
 v. Time investigation started: 14:32 HRS
 vi. Estimated quantity spilled: NOT APPLICABLE

4. Site Details

- i. Site/Location: 18" ASSA-RUMUEKPE P/LC RUMUEKPE, EMOHUA LGA, R/L
 ii. Position of Spill/Leak: N4.99365 E6.69514
 iii. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)
 iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☐ Others (Specify) NON-LEAK

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☐ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify) *N/A*

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
 Dead floating crabs
 Withering of vegetation
 Others (Specify) *N/A*

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii. *SK*
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii. *N/A*
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>SK</i>	<i>SK</i>	<i>SK</i>	<i>SK</i>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>SK</i>	<i>SK</i>	<i>SK</i>	<i>SK</i>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>SK</i>	<i>SK</i>	<i>SK</i>	<i>SK</i>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>SK</i>	<i>SK</i>	<i>SK</i>	<i>SK</i>

8. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

9. Samples taken.....

NTA

10. Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

11. Remarks/Recommendation

(i) REPAIRS OF THE PIPELINE SHOULD BE CARRIED OUT
(ii) SECURITY & SURVEILLANCE SHOULD BE IMPROVED ON SPDC'S FACILITIES.
(iii) POPULACE SHOULD BE SENSITIZED ON THE DANGERS OF ILLEGAL CRUDE REFINING

15:42 HRS

12. Time Investigation ended.....