

561028



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 10/08/2022    ii. Date first reported: .....  
 iii. Date of first investigation: 17/08/2022  
 iv. Date of follow-up investigation: NIL  
 v. Time investigation started: 14:30 Hrs  
 vi. Estimated quantity spilled: 30661s

4. Site Details

- i. Site/Location: 3" Oguta Well 6 L/s Flowlines  
 ii. Position of Spill/Leak: .....  
 iii. Spill area  
☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☒ Others (Specify) .....

iv. Structural Controls in Place

- ☒ Boom    ☒ Trenches    ☒ Bund Wall    ☒ Sorbents    ☒ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock    ☒ 10 0'Clock    ☒ 2 0'Clock    ☒ 3 0'Clock  
☒ 4 0'Clock    ☒ 5 0'Clock    ☒ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (Specify) .....

iii. Facility

- ☒ Pipeline    ☒ Flow Line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☒ Rig  
☒ Storage Tank    ☒ Compressor Plant  
☒ Others (Specify) .....

iv. Cause of Spill

- ☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☒ Others (Specify) mechanical cut



## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland   ☒ Fish Pond   ☒ Vegetation   ☒ Fishing Net   ☒ Surface water  
☒ Venerable Objects   ☒ Others (Specify) Pool of water outside the well head area

### ii. Nature of impact

- ☒ Oil stained vegetation   ☒ Oil stained fishing nets   ☒ Dead floating fishes  
☒ Dead floating crabs   ☒ Withering of vegetation   ☒ Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW   ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

i. Umuachaish

ii. ....

iii. ....

iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

i. 0.05 ha

ii. ....

iii. ....

iv. ....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |



8. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

9. Samples taken..... NIL

10. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

11. Remarks/Recommendation. SPDC should maintain their wellhead area to avoid further occurrence of crude getting into third party areas, they should immediately clean up the impacted areas.

12. Time Investigation ended.....

15:10 Hrs.