



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:
☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify) Illegal connection

3. Incident Details
i. Date of Incident: 25/03/2023 ii. Date first reported: 25/03/2023
iii. Date of first investigation: 12/04/2023

iv. Date of follow-up investigation: 12/15/11/23

v. Time investigation started: N/A

vi. Estimated quantity spilled: N/A

4. Site Details 24" Cough-Bond Pipeline at Nkoma, Falcian Rivers State
i. Site/location: 4.765891, 7.219806

ii. Position of Spill/Leak: N/A

iii. Spill area N/A
☐ Road ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastal

☐ Near shore ☐ Offshore ☐ Others (specify): N/A

iv. Structural Controls in Place N/A
☐ Boom ☐ Buoys ☐ Island wall ☐ Berthment ☐ Others (specify):

5. Circumstances Around Spill Point

i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock

☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant N/A
☐ Crude Oil ☐ Condensate ☐ Lubricants ☐ Refined Products
☐ Others (specify):

iii. Facility ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Valve Station ☐ Rig
☒ Spective ☐ Flow line ☐ Compressor Plant ☐ Others (specify):

iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify):

v. Visible Signs of Third Party Interference
☐ Backsaw Marks ☐ Drilled Holes ☐ Blasting ☐ Other ☐ Acid
☐ Others (specify): 1/5 well valve illegally installed on 1 line
pipeline at 12 o'clock problem by unknown person.

6. Impact of Incident

i. Properties impacted by the incident **N/A**

☐ If seabed ☐ If Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects ☐ Others (specify) _____

ii. Nature of impact **N/A**

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☐ Others _____

iii. Delineation of impacted area **N/A**

☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i. _____

ii. _____

iii. _____

iv. _____

b) Land (indicate area in m²)

i. _____

ii. _____

iii. _____

iv. _____

b) Creeks/ creek beds

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

e) Shoreline/water

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

8. Photographs/Maps/Chart/Ret.

☒ Still photographs

☐ Video coverage

☐ Mapping

9. Samples taken. H/A

10. Investigation carried out by

☒ Police

☐ Boat

☐ Aerial

11. Remarks/Recommendation (1) SPDC Should ensure the illegal

conveying and capture the affected part of the river

(2) SPDC should ensure improve on the security of the river

12. Time investigation ended 3:15:15