



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties to the field

1. Company: SPDC

2. Type of Complaint/Incident:

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify):

3. Incident Details

i. Date of Incident: 16/04/2023

ii. Date first reported: 16/04/2023

iii. Date of first investigation: 17/04/2023

iv. Date of follow-up investigation:

v. Time investigation started: 12:05 HR

vi. Estimated quantity spilled: 180 BBL'S

4. Site Details

i. Site Location:

24' Ogale-Boni Trench at Kpffe-Biara
Area, near St

ii. Position of Spill/Leak: 4-70782526N 7-27987820E

iii. Spill area

☒ Land

☐ Swamp

☐ Freshwater

☐ Near shore

☐ Offshore

☐ Others (specify):

iv. Structural Controls in Place

☐ Boom

☒ Trenches

☐ Blind wall

☐ Sorbents

☐ Others (specify):

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock

☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil

☐ Condensate

☐ Chemicals

☐ Refined Products

☐ Others (specify):

iii. Facility

☒ Pipeline

☐ Flow line

☐ Wellhead

☐ Storage Tank

☐ Compressor Plant

☐ Others (specify):

iv. Cause Of Spill

☐ Corrosion

☐ Equipment Failure

☒ Third Party Interference

☐ Operational Error

☐ Others (specify):

v. Visible Sign of Third Party Interference

☐ Blackaw Marks

☐ Drilled Holes

☐ Blasting

☐ Others (specify):

☐ Others (specify):

☐ Others (specify):

☐ Others (specify):

☐ Others (specify):

☐ Others (specify):

☐ Others (specify):

☐ Others (specify):

☐ Others (specify):

☐ Others (specify):

☐ Others (specify):

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Bermland ☒ Depth Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Vulnerable Objects ☐ Others (specify) _____

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others _____

iii. Delimitation of impacted area

☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Contaminant (indicate name)

- i. Kpife
 ii. Biara

b) Land (indicate area in m²)

- i. 0.2411K.
 ii.

iii.

iv.

b) Creek/Creek bed

☐ Total

☐ Down-stead

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

c) Swamp

☐ Total

☐ Down-stead

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

d) River

☐ Total

☐ Down-stead

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

e) Shoreline/water

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

1. Photograph Map Chart Not

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aerial

11. Remarks/Recommendation

and report of the investigation should be reviewed, the results of beat (2) SPDC should be provided to the relevant authorities. The results of beat 2501 of the investigation should be provided to the relevant authorities.

12. Time investigation ended.....

13. Name and Signature of Participants

♦ NOSDRA A. C. O. N. S. A. M. F. 17/04/2023