



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SPDC
2. Type of Complaint/Incident:
☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify) Illegal Connection
3. Incident Details
i. Date of Incident: 28/03/2023 ii. Date first reported: 28/03/2023
iii. Date of first investigation: 05/04/2023
iv. Date of follow-up investigation: _____
v. Time investigation started: 1:06 HRS
vi. Estimated quantity spilled: N/A
4. Site Details LGA Rivers State
i. Site/Location: 18" ASSA-Rumekpe pipeline at Olohia, Emuoha
ii. Position of Spill/Leak: 5.26741N, 6.77639E
iii. Spill area No-spill
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify) _____
iv. Structural Controls in Place N/A
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) _____
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☒ Others (specify) NOIL - LEAK
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify) _____
iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify) _____
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☒ Others (specify) 3" ball valve reduced to 2" theft line illegally installed on the 18" pipeline at 12 O'clock position by unknown person(s).

23/04/2023, 10:00

6. Impact of Incident

i. Properties impacted by the incident *N/A*

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact *N/A*

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i.

ii.

iii.

iv.

b) Land (indicate area in m²)

i.

ii.

iii.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Photograph Maps ☒ Data Ref. ☐ Mapping

Cell photographs ☐ Video coverage

☒ Yes, all photographs

☐ Videos or images

☐ All mapping

[illegible]

10. *How many people are employed by the firm?*

Abstract

[illegible]

Office	Date	Remarks/Recommendations
		(1) SPDC should remain the designated communication and reporting affected party in the line
		(2) SPDC should continue on the security of the line

12. Time investigation 2.24hrs

Alkene and Substitution of Polyolefins