

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken.....None

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation.....SPDC should be mandated to intensify surveillance in order to protect their facilities and assets.

12. Time Investigation ended.....2:25 pm

13. Name and Signature of Participants