






PHOTOGRAPHS TAKEN DURING THE PRELIMINARY INVESTIGATION AND JIV OF OIL SPILL AT ITAK IDIM UKPA



Valve installed on the pipeline sighted



L: R Two different impacted sites sighted during preliminary Investigations




SIGN POST OF UERL SIGHTED ON THE RIGHT OF WAY THAT LEADS TO SPILL SOURCE



L-R: Engr. Melvis Odobo and Dr. Arit Etim standing and briefing the elders and the JIT about the reason for the visit to the spill source.



The JIT observes and ask questions to UERL as two young men scoop out sand and water to reveal the full extent of the pipeline and valve



L-R: Two you young men scooping out sand and water and Valve fully revealed



L-R : Two different booms sighted few meters away from the installed valve on the pipeline



L-R: Members of the JIT, Engr. Melvis Odobo, Arc. Ekeminiubong, Ito Edet , Engr. Gaxton Okobah (NOSDRA), Foloki Francis (NUPRC) and one of the staff members of UERL



L-R: Dr. Arit Etim (UERL) thanking the JIT for a Good job, Engr. Aniefieh Emah (MPPD)