

594701



# **NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**

## **JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

### 2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) NOT LEAKING

### 3. Incident Details

- i. Date of Incident: 27/08/2022 ii. Date first reported: 28/08/2022  
 iii. Date of first investigation: 20/05/2023  
 iv. Date of follow-up investigation: 21/05/2023  
 v. Time investigation started: 13/0 Hrs  
 vi. Estimated quantity spilled: N/A

### 4. Site Details

- i. Site/Location: 14<sup>th</sup> Okor Lig Rumuekpa P/L QOSH: AWELEADIS  
 ii. Position of Spill/Leak: N5.071608 E6.559522

#### iii. Spill area

- ☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline  
☐ Near shore ☐ Offshore ☐ Others (Specify).....

#### iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify).....

### 5. Circumstances Around Spill Point

#### i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock  
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

#### ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products  
☒ Others (Specify) NOT LEAKING

#### iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig  
☐ Storage Tank ☐ Compressor Plant  
☐ Others (Specify) .....

#### iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident  
☐ Operational Error ☐ Others (Specify).....

#### v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid  
☐ Others (Specify) 3<sup>rd</sup> Ball valve for Oil theft print.

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☒ Others (Specify) HMA

### ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
Dead floating crabs Withering of vegetation Others (Specify) .....

### iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

i. ....  
ii. ....  
iii. ....  
iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

i. ....  
ii. ....  
iii. ....  
iv. ....

### (c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

### (d) Swamp ☐ Tidal ☐ Non-tidal

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

### (e) River ☐ Tidal ☐ Non-tidal

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

### (f) Shoreline/water ☐ Tidal ☐ Non-tidal

| NAME  | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|-------|--------------------|-----------------|----------------|
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |
| ..... | .....              | .....           | .....          |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken..... NIL

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation. Reports should be done and  
SPDC should improve on her surveillance.

12. Time Investigation ended.....

13. Name and Signature of Participants   /