



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: N A O C
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 29.05.23 ii. Date first reported: 29.05.23
iii. Date of first investigation: 29.05.23
iv. Date of follow-up investigation: N/A
v. Time investigation started: 1502 HRS
vi. Estimated quantity spilled: 30.02 BBLs
4. Site Details
i. Site/Location: 4" EBEGORO 12L FLOWLINE @ Omeku Comm. ONELGA
ii. Position of Spill/Leak: N 05° 23' 03" E 006° 39' 9.99"
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) N/A
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☒ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify).....
iii. Facility
☐ Pipeline ☒ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)..... *N/A*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others..... *N/A*

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. *Omoku*
 ii. *N/A*
 iii. *N/A*
 iv. *N/A*

b) Land (indicate area in m²)

- i. *1663.27 m²*
 ii. *N/A*
 iii. *N/A*
 iv. *N/A*

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<i>N/A</i>		

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<i>N/A</i>		

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<i>N/A</i>		

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<i>N/A</i>		

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... Clean-up of impacted area is advised
Repairs begun immediately and surveillance should also be
improved

12. Time investigation ended..... 1635 HRS

13. Name and Signature of Participants

❖ NOSDRA

1. OKPALA OBINSA  29/05/23

2.

3.


❖ DPR

1. 

2. 

3.

❖ STATE MINISTRY OF ENVIRONMENT

1. EBIKINGA SAPPA  29/5/2023

2.

3.


❖ LOCAL GOVERNMENT COUNCIL

1. 

2. 

3.

❖ COMPANY

1. AKPO-ISAAC OWIGI NAOC(HSE)  29/5/2023

2. Duncan Von Beke (SXD)  29/5/23

3.

❖ COMMUNITY

1. Ossia Inlisdan 

2. 29/05/2023

3.