

INC-NO. 1266040

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 08/07/2023 ii. Date first reported: 12/07/2023
iii. Date of first investigation: 15/07/2023
iv. Date of follow-up investigation:
v. Time investigation started: 1236 Hours
vi. Estimated quantity spilled: NO SPILL

4. Site Details

- i. Site/Location: 20" RUMUEKPE-NKPOKU TNP AT IBAA
ii. Position of Spill/Leak: N4.95495000 E6.79523352
iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) 3 N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☒ Others (Specify) NO SPILL

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hack saw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☒ Others (Specify) 3" BALL VALVE INSTALLED AT 12 O'CLOCK

Impact of Incident

i. Properties Impacted by the Incident

- ☐ Permeant ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venturite Objects ☐ Others (Specify) _____

} N/A

ii. Nature of Impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating corals ☐ Withering of vegetation ☐ Others (Specify) _____

} N/A

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

} N/A

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. _____
 ii. _____
 iii. _____
 iv. _____

} N/A

- (c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

- (d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

- (e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

- (f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

Investigation started at

First photograph ☐ Other ☒ Other ☐

Other notes: NOT IN THE LINE

Investigation carried out by

First ☐ Other ☒ Other ☐

Remarks: SPDC To carry out Referrals

SPDC Referral in Mil Level Surveillance

SPDC Referral should be taken seriously

Investigation ended 1520 hours