



17

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: Addax Petroleum Dev Ny Ltd
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 30/05/2010 ii. Date first reported: 31/05/2010
 - iii. Date of first investigation: 03/05/2010
 - iv. Date of follow-up investigation: —
 - v. Time investigation started: 11:43 HRS
 - vi. Estimated quantity spilled: 350 Barrels
4. Site Details
 - i. Site/Location: Anlan Terminal
 - ii. Position of Spill/Leak: N 04° 12' 00" E 08° 20' 15"
 - iii. Spill area
☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☒ Offshore ☐ Others (specify).....
 - iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
 - iii. Facility
☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☒ Others (specify) Export Hose
 - iv. Cause Of Spill.
☐ Corrosion ☒ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference N/A
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact *NIL*

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets *N/A*

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp *N/A*

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River *N/A*

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water *N/A*

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... NIL

10. Investigation carried out by

☒ Foot ☐ Boat ☒ Aircraft



11. Remarks/Recommendation

The exercise was a success. The company (Addax Pet. Dev Co. Ltd) should conduct a Post Impact Assessment exercise to ascertain the level of impact on the seabeds.

12. Time investigation ended 12.35 HRS

13. Name and Signature of Participants



❖ NOSDRA

1. EKANEM InE A.  03/06/2010
2. ADEOLA OLUFEMI J.  05/06/10
- 3.

❖ DPR

- 1.
- 2.
- 3.



❖ STATE MINISTRY OF ENVIRONMENT (AKMEMR)

1. SANKAY OFOWINKE E.  03/06/2010
2. ASUQUO, COMFORT TOM (Mrs)  03/06/2010
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY (Addax Petr. Dev Co)

1. SULAIMAN I. A ADDAX PETROLEUM  03/06/10
2. OLUFEMI AYoola ADDAX 
- 3.

❖ COMMUNITY

- 1.
- 2.
- 3.