



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required
Company Name		Mobil Producing Nigeria -MPN
Reporting Officer		Mark Fraser
Designation		General Manager, Joint Venture Operations
Phone Number		0817 207 3919
Email Address		mark.w.fraser@exxonmobil.com
Incident Number		12 / 2023
Section 2 - Location		
State / LGA		Yoho PP OML 104 - /
Coordinates of spill		EASTINGS 4Deg 9Min/0Secs N NORTHINGS 7Deg 29Min/45Secs E
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others
Depth of Water (if applicable)		
Section 3 – Spill Details		
Date and Time of spill		8/9/2023 Time: 13:20 hours local time
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....
Cause of spill		Corrosion: At about 1320hrs, during plant walkabout, sheen was observed on the eastern side of YP platform. Traced source to oily water leak (pinhole) on 2" LP fuel gas skid liquid drain line to the closed drain system on YP cellar deck - Leak was stopped.
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify) Leak was stopped using engineered stop kit.
Product Data	☐ Persistent ☐ Non Persistent	
	Product Name/Type	
	SG/API Gravity	
	Pour Point	
	Wax Content	
	Asphaltene	
	Sulphur Content	
Viscosity		

Oil	Slick Locations(s)		
-----	--------------------	--	--

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release	Continuous Release	
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00019bbl of oily water based on sheen appearance	
	Coverage	About 100m x 2m of 30% clear water, 20% rainbow colors and 50% silvery sheen on sea water.	
	Direction of travel		
Section 5 - Weather			
METEOROLOGICAL DATA			NIMET weather forecast
Wind Direction (wind direction given from)	North East		
Initial Wind Speed	11 knots		
Air Temperature (C or OF)	Air Temp 28°C		
Visibility Estimate	☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood	High ☐	Ebb ☐	
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning	Yes ☐	No ☒	
Recovery of free phase oil	Yes ☐	No ☒	
Booming	Yes ☐	No ☒	
Wild life rehabilitation	Yes ☐	No ☒	
Dispersant application	Yes ☐	No ☒	
Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐

