

1N-0304

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY **JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: HHOG
2. Type of Complaint/Incident:
- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
- ☒ Others (Specify) NON-LEAKING
3. Incident Details
- i. Date of Incident: 04/09/2023 ii. Date first reported:
- iii. Date of first investigation: 05/09/2023
- iv. Date of follow-up investigation:
- v. Time investigation started: 1650 HOURS
- vi. Estimated quantity spilled: NIL
4. Site Details
- i. Site/Location: 8" Umuechem-Nkpoku MAN. DELIVERY LINE
- ii. Position of Spill/Leak: PT 2 N 04 59 54.5 E 007 01 18.1 E 007 01 18.0
- iii. Spill area
- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
- ☐ Near shore ☐ Offshore ☐ Others (Specify)
- iv. Structural Controls in Place
- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)
5. Circumstances Around Spill Point
- i. Visual observation of Hole Position
- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
- ☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock
- ii. Type of Oil Contaminant
- ☒ Crude Oil. ☐ Condensate ☐ Chemicals ☐ Refined Products
- ☒ Others (Specify) NO SPILL
- iii. Facility
- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
- ☐ Storage Tank ☐ Compressor Plant
- ☐ Others (Specify)
- iv. Cause of Spill
- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
- ☐ Operational Error ☐ Others (Specify)
- v. Visible Sign of Third Party Interference
- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
- ☒ Others (Specify) NO SPILL

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
Dead floating crabs Withering of vegetation Others (Specify)

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. UMUWEHI
ii.
iii.
iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

Samples taken.....NOT APPLICABLE.....

Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

Remarks/Recommendation.....

CAUSE OF SPILL IS ESTABLISHED
AS SABOTAGE. HHOG TO COMMENCE REPAIRS
IMMEDIATELY.

Time Investigation ended.....

Name and Signature of Participants