

**JOINT INVESTIGATION VISIT (JIV) OF UERL SPILL INCIDENT ON AUGUST 16, 2013 CARRIED OUT ON AUGUST 19 2013**



**L-R: Asuquo, Nimchak (NOSDRA). Ukeme, Christian(Universal). Efiong, Boyler, Bassey (Community Reps). Onyeogali, (NOSDRA), Phillip(Universal), Nnamdi (NOSDRA) within UERL Well 7&8 premises.**



**2-3: Nimchak briefing the JIT ( Pic 2), Engr Phillip of Universal Energy briefing the JIT on the Spill Incident**





4



5

**4-5: An overview of the Spill Site within the UERL's Facility (Pic4). The JIT taking a Tour of the impacted Site (Pic5)**



6



7

**6-7: This empty space (Pic6) shows that Tank 5 that had a ruptured flange which caused spill has been isolated (Pic7)**



8



9

**8-9: The Spilled Crude within the parameter fence sighted (Pic8). JIT Inspecting the Spill Spot (Pic9)**





10



11

**10-11: Recovery pump (Pic10) and Recovered Crude sighted in Recovery containers (Pic11)**



12



13

**12-13: Spill covered with Sand to contain the Spill sighted (Pic12 and 13)**



14



15

**14-15: The JIT debriefing in UERL Camp. Members of the JIT signing the JIV form (Pic15)**