

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... SPDC SHOULD INCREASE
SURVEILLANCE ON THEIR PIPELINE FACILITY
TO AVOID FUTURE OCCURENCES

12. Time Investigation ended..... 12:55 HRS

13. Name and Signature of Participants