

✓ 11

checked

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: PPMC
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 10/8/2012 ii. Date first reported: 13/8/2012
iii. Date of first investigation: 11*/09/2012
iv. Date of follow-up investigation:.....
v. Time investigation started: 3:35pm
vi. Estimated quantity spilled:.....
4. Site Details
i. Site/Location: 1KM 76 ^{Aduma} N10.16326° E008.05548° (Kod-Job Axis)
ii. Position of Spill/Leak:.....
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify)..... NIL
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products
☐ Others (specify)..... PPMS
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)..... *NIL*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others... *NIL*

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

- i. *Ladduga Community*
 ii. *Aduma Village*
 iii. *Community*
 iv.

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *SL*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... *The exposed pms pipeline should be buried and security surveillance along the facility should be improved.*

12. Time investigation ended..... *5:52 pm*

13. Name and Signature of Participants

❖ NOSDRA

1. *Shutv malami Sff. 11/09/12*
- 2.
- 3.

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY

1. *PPMC*
2. *ONUVA M.E*
3. *Thompson 13/09/12*

❖ COMMUNITY

- 1.
- 2.
- 3.