



Handwritten signature

✓ 58

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: KABIRU GUSAU (LPB SUPPLIER)
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) ACCIDENT INVOLVING OIL TANK
3. Incident Details
i. Date of Incident: 12/07/2012 ii. Date first reported: 13/07/2012
iii. Date of first investigation: 13/07/2012
iv. Date of follow-up investigation: _____
v. Time investigation started: 6:30 PM
vi. Estimated quantity spilled: 33 000 LITRES
4. Site Details
i. Site/Location: KADARI BRIDGE
ii. Position of Spill/Leak: N 12.34907°, E 006.34191°
iii. Spill area
☒ Land ☐ Swamp ☒ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☒ Others (specify) RIVER (KADARI)
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) _____
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☒ Others (specify) LPFO
iii. Facility
☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☒ Others (specify) TANKER
iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☒ Accident
☐ Operational Error ☐ Others (specify) _____
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) _____

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☒ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☒ Others..... *SOURCE OF WATER TO A DAM*

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by



☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....
 ① A follow-up investigation must be carried out by the Agency to ascertain the extent of impact of the washed oil along the river. ② The supplier of the oil should be identified

12. Time investigation ended.....

13. Name and Signature of Participants

❖ NOSDRA

1. MUTSHO W ALEXANDER D. 
2. AMINY ABBA 
- 3.

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

1. MOUKTAR LUGGA HON. COMM. ENVIRONMENT
2. Korbine Sam Hon. Flood & Erosion co. Dupa
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY

- 1.
- 2.
- 3.

❖ COMMUNITY

- 1.
- 2.
- 3.