



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

- 02
1. Company: PPMC
 2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
 3. Incident Details
 - i. Date of Incident: 23-05-2011 ii. Date first reported:.....
 - iii. Date of first investigation: 16-06-2011
 - iv. Date of follow-up investigation:.....
 - v. Time investigation started: 10:15 am
 - vi. Estimated quantity spilled: 15,000 lbs
 4. Site Details
 - i. Site/Location: KM 149 N09.32395°E 007.00732°Z 369m
 - ii. Position of Spill/Leak:.....
 - iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
 - iv. Structural Controls in Place
☐ Boom ☒ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
 5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
 - iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. Gurara Village
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. Spill covered area
 ii. about 1km long and
 iii. 60 meters wide.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken

Top Soil

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation


The Site Should be cleaned up and remediated.

12. Time investigation ended

13. Name and Signature of Participants

❖ NOSDRA

1. ISA Yunus, Chedi
2. Shitu Malami
3. BAFIYA ABBAS M.


SA.
Sagbala.

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT


- 1.
- 2.
- 3.


❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY

1. PDMC.
- 2.
- 3.


Okpanacha M.A. 16/06/2011
SINISUPT.


Onu Y.A. - Y.E 16/04/11

080 35885505

❖ COMMUNITY

- 1.
- 2.
- 3.