

Checked

B 911

APPENDIX 11-3

JOINT INVESTIGATION VISIT (JIV) REPORTING FORM



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: PPM C/NNPC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 03/04/13 ii. Date first reported: 04/04/13
iii. Date of first investigation: 05/04/13
iv. Date of follow-up investigation:
v. Time investigation started: 12:10 PM
vi. Estimated quantity spilled: N/A

4. Site Details

- i. Site/Location: Km 45, TUNA, GURARA LGA, NIGER STATE.
ii. Position of Spill/Leak: WP 128 NO9.36191 006.85346 Z 348
iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify)..... N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O. Clock ☐ 10 O. Clock ☐ 2 O. Clock ☐ 3 O. Clock
☐ 4 O. Clock ☐ 5 O. Clock ☐ 6 O. Clock

ii. Type of Oil contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products
☐ Others (specify).....

iii. Facility

- ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause Of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (specify)..... *N/A (already clamped & buried)*

6. Impact of Incident

i. Properties Impacted by the Incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects ☐ Others (specify)..... *NO impact*

ii. Nature of Impact

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☐ Others..... *N/A*

iii. Delineation of Impacted area

☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (Indicate name)

- i.
ii.
iii.
iv.

b) Land (Indicate area in m²)

- i.
ii.
iii.
iv.

b) Creeks/Creeklets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

B 913

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☐ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken. None

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation... Improved Security Surveillance on your facilities is highly recommended

12. Time Investigation ended.....

13. Name and Signature of Participants

❖ NOSDRA
1. TAMER, Ibrahim I. afhis
2. USMAN, Hindu afhis
3. BAKARI, Umar A. afhis

❖ DPR
1.
2.
3.

❖ STATE MINISTRY OF ENVIRONMENT
1.
2.
3.

B 914

❖ LOCAL GOVERNMENT COUNCIL

1. _____
2. _____
3. _____

❖ COMPANY

1. *PPMS*
ON 11/17 *Y.E* *[Signature]*
2. _____
3. _____

05/04/13

❖ COMMUNITY

1. _____
2. _____
3. _____