



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: P.P.M.C.
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 5/9/2011 ii. Date first reported: 06/9/2011
iii. Date of first investigation: 8/9/2011
iv. Date of follow-up investigation:.....
v. Time investigation started: 3:09 pm
vi. Estimated quantity spilled: NTD but massive
4. Site Details
i. Site/Location: KUNA 189 2C
ii. Position of Spill/Leak: N09.66667° E007.07948°
iii. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☒ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
- iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
- iv. Cause Of Spill
☒ Corrosion ☒ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
- v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. Kuna.....
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 715.....
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken..... Soil & water

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

The exact point of rupture is not yet known, as at the time of investigation, an excavator is on site digging the soil to exposed the pipeline.

12. Time investigation ended..... 7:00pm

13. Name and Signature of Participants

❖ NOSDRA

1. SAFIYA ABBAS M. Sazb...
2. YUSUF MANDOKI Tanimu *[Signature]*
3. HAYATUDDdeen IBRAHIM ISA *[Signature]*
(NYSC)

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY

1. OKPANACH? M. A *[Signature]* 8/9/2011
2. Abbas H.B. *[Signature]*
3. ONUYA .Y.E *[Signature]* 08/09/11
08/9/2011

❖ COMMUNITY

1. AITA KUNA (ward Head) 08153328828 *[Signature]*
2. MOSES AITA 08152328831 *[Signature]*
- 3.