



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: PPMC
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) Refined product (PMS)
3. Incident Details  
i. Date of Incident: 28-10-12    ii. Date first reported: not reported  
iii. Date of first investigation: 29-10-13  
iv. Date of follow-up investigation: \_\_\_\_\_  
v. Time investigation started: 10:40 AM  
vi. Estimated quantity spilled: \_\_\_\_\_
4. Site Details  
i. Site/Location: 1KM 3 RIBO VILLAGE, KADUNA  
ii. Position of Spill/Leak: N. 10.40187, E 007.51782, Z 592m  
iii. Spill area  
☒ Land    ☐ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (specify) \_\_\_\_\_  
iv. Structural Controls in Place  
☐ Boom    ☐ Trenches    ☐ Bund wall    ☒ Sorbents    ☐ Others (specify) \_\_\_\_\_
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☒ 12 O' Clock    ☐ 10 O' Clock    ☐ 2 O' Clock    ☐ 3 O' Clock  
☐ 4 O' Clock    ☐ 5 O' Clock    ☐ 6 O' Clock  
ii. Type of Oil contaminant  
☐ Crude Oil    ☐ Condensate    ☐ Chemicals    ☒ Refined Products  
☐ Others (specify) \_\_\_\_\_  
iii. Facility  
☒ Pipeline    ☐ Flow line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant    ☐ Others (specify) \_\_\_\_\_  
iv. Cause Of Spill  
☐ Corrosion    ☐ Equipment Failure    ☒ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (specify) \_\_\_\_\_  
v. Visible Sign of Third Party Interference  
☐ Hacksaw Marks    ☒ Drilled Holes    ☐ Blasting    ☒ Theft    ☐ Acid  
☐ Others (specify) \_\_\_\_\_

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☐ Surface water  
☐ Venerable Objects   ☐ Others (specify)..... **No Impact** .....

ii. Nature of impact

- ☐ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☐ Withering of vegetation   ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW   ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m<sup>2</sup>)

- |           |           |
|-----------|-----------|
| i. ....   | i. ....   |
| ii. ....  | ii. ....  |
| iii. .... | iii. .... |
| iv. ....  | iv. ....  |

b) Creeks/Creek lets   ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

c) Swamp   ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

d) River   ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken... No

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

Security Surveillance  
should be improved upon.

12. Time investigation ended... 11:00 AM

13. Name and Signature of Participants

❖ NOSDRA

1. SHEHU A. YUSUF [Signature] 29/10/13
2. YUSUF M. TANIMU [Signature]
3. ARSLAN MAHDE [Signature]

❖ DPR

1. Beda S. Kereb [Signature]
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY

1. BELLO J.M [Signature] 29/10/13
- 2.
- 3.

❖ ~~COMMUNITY~~ NSCDC

1. OGUNTUASE MICHAEL [Signature] 29/10/13
- 2.
- 3.